

**Illinois Commerce Commission
Pipeline Safety
Field Trip Report**

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Exit Meeting Contact: Dallas Jett	Total Man Days: 2
Pipeline Safety Representative(s): Randall Stewart	
Company Representative to Receive Report: Michael Fuller	<u>Emailed Date:</u>
Company Representative's Email Address: mfuller2@ameren.com	11/29/2012

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection - Field Audit	Tuscola	Randall Stewart	Tuscola	2	9/27/2012, 9/28/2012	Dallas Jett, Fred Halabi, John Reardon

Statement of Activities

On the above dates a field inspection was conducted of the Ameren Illinois Tuscola inspection unit. The purpose of the inspection was to determine compliance with the code sections identified on the attached inspection forms. The inspection included numerous facilities which are identified in the comments sections of the inspection forms.

ISSUE(S) FOUND:

192.365(c) - The meter set at 303 Holiday Drive was noted to have a buried stopcock. A brick patio had been constructed around the service line to the top of the stopcock leaving only the top of the nut visible. Ameren exposed the service line and replaced the stopcock. While performing a follow-up inspection a class 3 leak was detected at the regulator vent. The customer was not at the residence. The regulator will be replaced. At the close of this audit a pipe to soil reading had been obtained, and the regulator is in the process of being replaced.

ISSUE(S) CORRECTED:

NO ISSUES CORRECTED.

NOTICE OF AMENDMENT(S) FOUND:

NO NOAS FOUND.

NOA(S) CORRECTED:

NO NOAS CORRECTED.

NOTICE OF PROBABLE VIOLATION(S) FOUND:

NO NOPVS FOUND.

NOPV(S) CORRECTED:

NO NOPVS CORRECTED.